


Suggestion for Flashing Cross Walls in Garaports Etc

The following suggested installation meets the BAL (Bushfire Attack Level).



Engineering Logic

This wall can now be considered as an end wall where no lapping of top hats is required. At *worst* using thicker gauge top hats at reduced length **or** only adding screw plates (see diagram below, on left) fixes this problem, as an alternative measure.

